

8寸工业监视器使用说明书



◆ 按键便捷操作 ◆



十字线左右移动
The crosshair moves left and right



十字线上下移动
The crosshair moves up and down



菜单键
menu



十字线开启/关闭、
长按2S可复位十
字线到中心点
Cross hair on/off, long press 2S to reset
Cross line to center point



电源按键 可关机、
开机
The power button can be turned off, Boot

◆ 标准配件 ◆

电源适配器 Power adapter	X1
牛角底座 Ox horn base	X1
立柱 Column	X1
底座贴纸 Base sticker	X1
说明书 Instructions	X1



◆ 规格参数 ◆

产品名称 product name	工业监视器
屏幕分辨率 Screen resolution	1024(RGB)x768
显示区域 Display area	162.048(H)x121.536(V)
屏幕比例 aspect ratio	4:3 (H:V)
对比度 Contrast ratio	800:1 (Typ.)
可视角度 visible angle	89/89/89/89 (Typ.)(CR ≥ 10)
亮度 Brightness	300 cd/m ²
响应时间 Response time	≤ 12m/s
刷新率 refresh rate	60HZ-75HZ
制式 standard	PAL/NTSE自适应
工作温度 Working temperature	(0℃-50℃)
语言 Language	中英文(默认中文)
视频接口 Video interface	BNC
电源 Power Supply	12V2A
整机功率 Whole machine power	≤ 10W
外观尺寸 Appearance dimension	200mmx165mmx33mm
壁挂尺寸 Wall hanging size	75mmx75mm
包装尺寸 Packing size	330mmx250mmx70mm

注意事项

- 1、十字线调整移动后会自动保存数据、复位后可回到中心点。
After the reticle is adjusted and moved, it will automatically save the data and return to the center point after reset.
- 2、屏幕避免尖锐物品或者硬物接触敲打防止刮花、破屏现象。
Avoid sharp objects or hard objects touching the screen to prevent scratches and screen breakage.
- 3、车载用时请使用12V稳压电源、避免电压不稳定烧坏机器。
Please use 12V regulated power supply to avoid burning the machine due to unstable voltage.

产品六视图

