
Factory Audit Report

1. Factory Profile:

Report no.: 20211016

General Information:						
Factory name: XXXXX CORPOR			IMITED			
Website:	http://www.XXXXX-o	corp.con	n/			
Address:	XXXXXXXX, MaXX Guangdong, China	XXXXXXX, MaXXXXXrial Park, No. 13, Donghuan 2th Road, Huangjiang, Dongguan,				
Date of the factory founded:	2017,5.23	5.23 Legal status: Body Corporate		ody Corporate		
Registered fund:	/	/				
Factory space (m ²):	3000m ²					
Annual international sales(USD):	90,000,000					
Annual Sales(total)(USD):	90,000,000					
Major products	Computer Hardware	;				
Major markets:	EU/USA/Middle Eas	st				
Contact Details:						
Owner of the plant: Ale	x Kung	Salesman:		Echo Lee		
Telephone #: xxx	хххххххх	Teleph	Telephone #: xxxxxxxxxxxxxxxx		XXXXXXXXX	
Mobile phone: N/A	l.	Mobile	phone:	xxxxxxxxxxxx		
Email address: xxx	ххххххххх	Email a	nail address: xxxxxxxxxxxxxxx		XXXXXXXXXX	
Main Clients:						
Country Buyer	Product Descrip	tion	Specificat	ion	Money/year	
USA SRV	Hardware		N/A		USD 450,000	
EU KCDD	Hardware		N/A		USD 200,000	
Staff information:						
Number of direct boa memebers	ard /	Number of workers:			89	
Number of Sample maker:	/	Number of QC:			10	
Number of sales people:	30(remark 8)	Number of office staf		affs	180(remark 8)	
Designer:	/					
Others:						





2. Business license:



Pictures about the factory:







Workshop

Workshop



Full check area

Incoming Material storage







Incoming Material warehouse

Fire extinguisher





	N/A
Semi-finished goods area	N/A

6. Production Lines/Capacity:

Main Clients:					
#	Machine Name	Machine Count	Capacity/Hour/Machine	Capacity/Month (8hrs/manday)	
1	SMT Line	6	/	VGA/Motherboard 200K pcs/Month	
2	DIP Line	2	1	Cooler 400K pcs/Month	
3	Packing Line	2	/		


7. Question List:


Incon	ning material area:		
#	Questions	Comment (Y/N)	
1	Are incoming materials inspected based on drawings/specifications?	Y	
2	Are incoming materials supplied with the manufacturer's warranty?	Y	
3	Is there a rejected material sample board for workers' reference? N		
Manu	facturing process area:		
#	Questions	Comment (Y/N)	
1	Is there any manufacturing procedure?	N	
2	Is all work instruction manual available at each work station?	Ν	
3	Is 5S system implemented at the production floor?	Ν	
4	Are rejected and accepted products clearly separated with clear signal?	Ν	
5	Is there any machine maintenance procedure?	N	
6	Is machine maintenance conducted periodically?	Y	
Quali	ty control and final inspection:		
#	Questions	Comment (Y/N)	
1	Is there any Quality Manual / Procedure?	Υ	
2	Is there Final QC?	Y	

Order Information:				
#	Questions	Comments		
1	Do you require a minimum order, either in dollars or quantity?	Minimum Qty: 900pcs or 1 CTN depends on		
		the product.		
2	Lead time for mass production:	7-40days depends on the product.		
3	Accepted payment condition:	30% deposit/ TT in advance		
4	Nearest Port/airport:	Shenzhen/HongKong		
5	Delivery/Loading Conditions:	N/A		
6	Do you have peak production/business periods – at	NO		
	what times of the year?			
7	How do you follow the order?	N/A		


Basic i	inspection to the products:		
#	Product Description	Testing Items	Comments(PASS or FAIL?)
1	Graphics card	/	/
Relate	ed pictures for the inspected products:		
۲odu	uct description:		
			RADEON BEEB BID BOORS













Function test

Card data

		Mainting for miner start . OK 2021-10-15 19142:00 Himer nut started yntill 2021-10-15 19142:00 Himer nut started yntill 2021-10-15 19142:00 Himer nut started yntill 2021-10-15 19142:13 Himer nut started yntill 2021-10-15 19142:14 Himer nut started yntill 2021-10-15 19142:24 Himer nut started yntill 2021-10-15 19142:25 Himer nut started yntill
Function test	transum transfer tran	Function test(remark 6)
Function tes		runcion test(remark o)

Auditor Comments:

1) AFOX Corporation, the professional graphics card and motherboard manufacturer with the reputed brand named "AFOX" presents reliable products for the key players from America/Europe/Middle East/South East Asia in PC industry. They said they created the total value of 90 million dollars of exporting PC components and this number still growing.

2) Factory is busy working and 3 production lines were running. 2 Packing lines were packing the graphics cards.

Warehouse on 1st floor is full of goods ready for shipment.

3) Due to technical confidential issues, the factory doesn't allow us to take photos of production process, especially for the equipments.

4)The factory refused to provide internal doucment for audit view.


5)No found working instrucment on the production line.

6) The APP can not running to check the working function due to Chinese coverment limited.

7) The factory can not provide QC doucment for audit view.

8) During visiting, inspector found there are about 8 employees in the office of the factory, but factory claimed they have 180 office people including 30 sales beside their factory but we can not visit.

Auditor	Tony	Date:	16-OCT-2021



Sales calling card

ShenZhen office